

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 17 ALDEN ST
Building ID 370
Parcel No. (PID) 12-1-040-0
Mapbase # 12-1-040
Building Area 81.265
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1850-1870
Source NR Nomination
Style/Form Astylistic
Architect/Builder
Exterior Material vinyl
Foundation brick
Wall/Trim vinyl, wood
Roof Side gable
Outbuildings/Secondary Structures
 1 outbuilding near Standish St.

Major Alterations (with dates)

Vinyl siding; addition & sash (1970-1980)

Condition Good
Moved no yes **Date**
Acreage 0.115
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

17 Alden Street is a 2-story, 3-4 bay building with a side gable roof. The primary façade is oriented to the south. The roof is clad in asphalt shingles; shed dormer on south slope; partial returns; frieze below the eaves. The building is clad in vinyl siding, except for the wood shingle cladding at the rear (northeast) façade. The primary entrance contains a pane and panel wood replacement door with wood screen; it is accessed by brick steps. A secondary entrance is located at the southeast corner. Fenestration includes 1/1 wood DHS, 1/1 wood awning, and Chicago-style windows. A 2nd-floor door is located on the southern façade, but it is suspended with no exterior access. A partially visible secondary entrance on the northeast elevation consists of a shed-roof section clad in wood shingles with a Chicago-style window and accessed by wood steps.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*