

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Town Provincetown
Place *(neighborhood or village)*
Address 88 BRADFORD ST
Building ID 1862
Parcel No. (PID) 11-3-061-0
Mapbase # 11-3-061
Building Area 604.651
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1830-1850
Source NR Nomination
Style/Form Eclectic
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Major Alterations *(with dates)*

Victorian details, c. 1900; shed dormer.

Condition Good
Moved no yes **Date**
Acreage 0.044
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date *(month/year)* 3/8/2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

88 Bradford Street is a 1-story, 2-bay sidehall cottage. The primary entry is reached by concrete and brick steps and landing. The door has multi-pane sidelights and an elaborate pedimented hood, with dentils and a unique appliqué. The detail is repeated on the window surrounds on the primary façade. A storm door is present. Windows are paired 2/1 wood DHS with storm windows. There is a band of diamond-shaped shingles across the gable end below the window. There is a large shed dormer located on the west side roof slope. Windows on this façade are grouped 2/1 DHS with storms. There is a 2nd entry here with concrete stoop. This façade has 2 diamond-shaped windows in the dormer and on the 1st floor. Walls contain bands of staggered shingles. Basement level windows on front façade are 2/1 DHS. The right side façade contains paired and single 2/1 DHS and 6/6 DHS windows. Central secondary entry at grade (basement) level. A window is located in an enclosed former entry. Windows have wood trim. Stuccoed chimney on side roof slope.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*