

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 4 WEST VINE ST
Building ID 1227
Parcel No. (PID) 06-2-046-0
Mapbase # 06-2-046
Building Area 1525.95
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1775
Source Tax assessment
Style/Form Italianate
Architect/Builder
Exterior Material wood shingle
Foundation stuccoed
Wall/Trim wood
Roof Irregular
Outbuildings/Secondary Structures

Major Alterations (with dates)

2nd story added with Italianate details, late 19th-century additions.

Condition Good
Moved no yes **Date**
Acreage 0.119
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

4 West Vine Street is a 2-story, 4-bay, 3/4 cottage with hipped roof. Brick chimney centrally located on roof ridge. A small cornice wraps around between 1st and 2nd stories. Main entrance is accessed by a multi-pane-and-panel door with storm door, sheltered by a flat hood supported by elaborate brackets. Fenestration includes grouped 4/1 and 6/1 DHS to left of door, 2 single 6/1 DHS to right of door, 2nd-story windows are 2/2 DHS. Inoperable shutters. Brackets line the main roof eaves. Building faces Commercial Street/water. The rear of the building, with steeply sloping roof, indicates that 2nd story was added to front and east side, likely when Italianate details were added. Entry at 1st floor, and exterior stair to 2nd story entry at east end. 1-story gable roof addition on west end. Separate panel door entry with storm, and 6/1 DHS. 1-story gable-roof extension from rear of this addition has 6/6 DHS window and separate entry.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*