MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Town Provincetown

Place (neighborhood or village)

Address 9 WEST VINE ST

Building ID 1914

Parcel No. (PID) 06-2-057-0

Mapbase # 06-2-057

Building Area 1231.188

Historic Name

Present Use Residential
Original Use Residential

Date of Construction 1870

Source 1977 Survey
Style/Form Italianate

Architect/Builder

Exterior Material clapboard

Foundation brick
Wall/Trim wood

Roof Side gable

Outbuildings/Secondary Structures

Major Alterations (with dates)

Condition Good

Moved ✓ no ☐ yes Date

Acreage 0.078

Setting

Recorded by Vanessa Zeoli

Organization Kise Straw & Kolodner

Date (month/year) April 2004

Form Status ☐ new ☑ update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSI		ON			
FORM B - BUILDING					
ADCUITECTURAL DESCRIPTION	and continuation above	•			•
ARCHITECTURAL DESCRIPTION Describe architectural feaures. Evaluate the characteristi	see continuation shee				
9 West Vine Street is a 2-story dwelling with 7-bays or on both roof slopes; interior brick ridge chimney; fenes and operable shutters on the 1st floor and a 7-bay she of the north façade has 6/6 wood DHS with wood surn the entrance on the south façade is accessed by a pa on the north façade is accessed by a wood panel doo façade.	n south, 8-bays on north; side stration on the south façade in ed dormer with 2 sets of group ounds and entablature lintels, une-and-panel wood door with	e-gable roof is sheathencludes 6/6 wood DHS with and the 2nd floor has modern storm and a f	ed in asphalt shingle S with wood surround h partial returns on a a 6-bay shed dorm flat hood supported	ds with er the 2nd flo er and 6/1 by bracke	ntablature lintels bor; the 1st floor I wood DHS; ts; the entrance
HISTORICAL NARRATIVE	see continuation shee	t			
Discuss the history of the building. Explain its association played within the community.			ng, and the role(s) the	? owners/o	ccupants
BIBLIOGRAPHY and/or REFERENCES	see continuation shee	t			
Recommended for listing in the National Regist Criteria Statement form.	ter of Historic Places. <i>If check</i>	red, you must attach a	completed Nationa	l Register	