# MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

### MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

### Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.



## **Sketch Map**

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Town	Provincetown
Place (neighborhood or village)	
Address	6 NICKERSON ST
Building ID	1586
Parcel No. (PID)	06-2-073-0
Mapbase #	06-2-073
Building Area	1240.039
Historic Name	Herman Smith House
Present Use	Residential
Original Use	Residential
Date of Construction	1800-1830
Source	NR Nomination
Style/Form	Astylistic
Architect/Builder	
Exterior Material	clapboard
Foundation	brick
Wall/Trim	wood
Roof	gable and ell
Outbuildings/Secondary Structures	

1 shed

Major Alterations (with dates)

additions

Condition Moved Acreage Setting Good ☐ no ☑ yes Date 0.082

Recorded byJOrganizationKDate (month/year)A

Johnette Davies Kise Straw & Kolodner April 2004

Form Status Assessor's Number new update USGS Quad Area(s)

Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

Provincetown

## MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

#### ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural feaures. Evaluate the characteristics of this building in terms of other buildings in the community.

6 Nickerson Street is a 1 1/2-story, 3-bay dwelling with 1-bay side ell that extends to the rear. A gable dormer is present on the front roof slope of the side ell, and a shed dormer is located on the rear roof slope. The main entry consists of a pane and panel door and multi-light storm. Door surround comprised of sidelights and entablature. Fenestration includes wood 6/6 DHS windows with operable shutters; side ell has multi-light semi-circular bay; 10-light awning in gable dormer. A 1-story gable roofed ell with separate entry extends from south side, westward. It has a brick chimney at the western gable end; slate roof on the north slope. A multi-light bow window and entry door are located on the north façade of this ell. Wood shingles on side facade. Exterior steps lead to a 2nd-floor rear entry.

#### HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

**BIBLIOGRAPHY and/or REFERENCES** 

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*