

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Town Provincetown
Place (*neighborhood or village*)
Address 12 COTTAGE ST
Building ID 138
Parcel No. (PID) 06-4-043-0
Mapbase # 06-4-043
Building Area 1201.491
Historic Name
Present Use Residential
Original Use Residential - Single-unit
Date of Construction 1847
Source Tax assessment
Style/Form Greek Revival
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof gable front & ell
Outbuildings/Secondary Structures
 2 secondary structures

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Major Alterations (with dates)

Main entry removed (1960s).

Condition Good
Moved no yes **Date**
Acreage 0.128
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (*month/year*) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

This building is a 1 1/2-story, 3-bay cottage with setback ell. Brick chimney on ell roof ridge; new chimneys on main roof slope; partial cornice returns and frieze; corner pilasters. Primary entry, located on the side ell, consists of a modern door and storm. An exterior stair leads to 2nd story entry on south gable end of ell; area under stair screened with lattice. Fenestration includes 2/1 and 6/6 DHS with storms. Main gable front has multi-light picture windows with flanking 2/1 DHS. 2/2 DHS on north facade, and 3/3 DHS just below eaves. Deck along ell.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*