

# MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION  
MASSACHUSETTS ARCHIVES BUILDING  
220 MORRISSEY BLVD  
BOSTON, MA 02125

### Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



### Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

**Town** Provincetown  
**Place** (neighborhood or village)  
**Address** 12A PLEASANT ST  
**Building ID** 184  
**Parcel No. (PID)** 06-4-124-0  
**Mapbase #** 06-4-124  
**Building Area** 596.916  
**Historic Name**  
**Present Use** Residential  
**Original Use** Residential  
**Date of Construction** 1870  
**Source** Tax assessment  
**Style/Form** Astylistic  
**Architect/Builder**  
**Exterior Material** wood shingle  
**Foundation** obscured  
**Wall/Trim** wood  
**Roof**  
**Outbuildings/Secondary Structures**

### Major Alterations (with dates)

Addition.

**Condition** Good  
**Moved**  no  yes **Date**  
**Acreage** 0.046  
**Setting**

**Recorded by** Vanessa Zeoli  
**Organization** Kise Straw & Kolodner  
**Date** (month/year) April 2004  
**Form Status**  new  update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

# MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

--	--	--	--

### ARCHITECTURAL DESCRIPTION

see continuation sheet

*Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.*

12A Pleasant Street appears to have been a gable-roofed cottage - this comprises the main building section. Additions have altered the appearance of this building. The main section has a brick chimney at the roof ridge and simple wood trim. An addition on the east façade extending south contains a plank entry door and 6-light awning windows. This roof is clad in wood shingles. An addition at the west facade, extending south, has a concrete block chimney. Other windows are 6/6 wood DHS. Wood steps lead to a porch across the south facade of the main block; this porch is framed by a wood shingle-clad half wall. A half wall also surrounds the northeast corner of the building.

### HISTORICAL NARRATIVE

see continuation sheet

*Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.*

### BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*