

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 32 BRADFORD ST
Building ID 968
Parcel No. (PID) 06-4-145-0
Mapbase # 06-4-145
Building Area 936.96
Historic Name
Present Use Residential - Multi-unit
Original Use Commercial
Date of Construction 1870-1890
Source NR Nomination
Style/Form Astylistic
Architect/Builder
Exterior Material asbestos shingle
Foundation brick
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures
 cottage

Major Alterations (with dates)

Residential conversion, mid-20th c.

Condition Fair
Moved no yes **Date**
Acreage 0.104
Setting

Recorded by Johnette Davies

Organization Kise Straw & Kolodner

Date (month/year) 2/18/2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

This is a 2-story, 3-bay former commercial building. The door is centrally located on the gable end, which faces Bradford Street. There are partial cornice returns at the gable end, and a simple cornice runs the length of the side façade of the building. Windows are single and paired 2/1 DHS with storms and wood surrounds. Wood window surrounds are intact. The left side façade facing Pleasant Street contains single and paired 2/1 DHS with storms and wood surrounds. A secondary entrance is located at rear and contains a pane and panel door, deteriorated flat roof hood, end brackets and brick stoop. Basement windows on this façade have 3-lights. The right side façade contains two 1/1 DHS with storms and surrounds and a brick stoop to a secondary entry at rear with small shed hood. The rear façade has 2/2 DHS and 2/1 wood DHS, replacement paired casement windows and 6-light basement windows. A section of shingles has been removed showing clapboard underneath.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*