

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place *(neighborhood or village)*
Address 10 PLEASANT ST
Building ID 46
Parcel No. (PID) 06-4-153-0
Mapbase # 06-4-153
Building Area 1056.612
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1850
Source NR Nomination
Style/Form Greek Revival
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures

Major Alterations *(with dates)*

Additions.

Condition Good
Moved no yes **Date**
Acreage 0.073
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date *(month/year)* April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

10 Pleasant Street is a 1-1/2-story, 3-bay, 1/2 cottage. The front-gable roof has partial cornice returns and a large frieze below the eaves. A gable dormer is located on the south roof slope, as well as 2 brick chimneys. Corner pilasters appear to support the large frieze. The main entry is a panel door with storm, flanked by sidelights. The door surround includes an entablature and pilasters that match the corner pilasters of the main building. Windows are 6/6 wood DHS with storms. A rear ell extends the southern half of the building westward, extending the main roof slope. Windows on the south facade are 2/1 DHS. The rear section of the added section has a break in the roof, which extends from the building southward to create an entry bay. This entry is located on the east facade, and a parapet wall above carries the main frieze across this façade. A small entablature is located above the door. A side gable roof section also extends northward from the rear ell. This has an entry on the east facade, and 2/2 and 1/1 DHS windows in this 3-bay facade.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*