MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Town Provincetown

Place (neighborhood or village)

Address 6 MONTELLO ST

Building ID 1584

Parcel No. (PID) 06-4-164-0 **Mapbase #** 06-4-164

Building Area 748.055

Historic Name

Present Use residential
Original Use Residential
Date of Construction 1830-1850

Source NR Nomination

Style/Form

Architect/Builder

Exterior Material wood shingle

Foundation brick
Wall/Trim wood

Roof Side gable

Outbuildings/Secondary Structures

Major Alterations (with dates)

Rehabilitation, c. 2002; fenestration change.

Condition Good

Moved ✓ no ☐ yes Date

Acreage 0.048

Setting

Recorded by Johnette Davies

Organization Kise Straw & Kolodner

Date (month/year) April 2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION		ON			
FORM B - BUILDING					
ARCHITECTURAL DESCRIPTION	see continuation sheet				
Describe architectural feaures. Evaluate the characteristic.			ımunity		
6 Montello Street is a 2-story, 3-bay sidehall cottage wi has partial returns and a frieze below the eaves. The n by knee braces shades the door; wood stoop. A wood A basement level entry is located below the deck. Fen windows on the north façade.	th a front gable roof. There a nain entry is a panel door wit I deck leads to a full pane do	are a brick chimney a h wood storm and sin uble door secondary	nd skylights at the s nple wood trim. A s entry at the rear por	shed roof had the	hood supported e south façade.
HISTORICAL NARRATIVE	see continuation sheet				
Discuss the history of the building. Explain its associations played within the community.			ing, and the role(s) th	e owners/o	occupants
Rehabilitation, c. 2002. Fenestration change. See tax	assessor's photographs				
BIBLIOGRAPHY and/or REFERENCES	see continuation sheet				
Recommended for listing in the National Register Criteria Statement form.	er of Historic Places. If checke	ed, you must attach a	a completed Nationa	ıl Register	r