

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Town Provincetown
Place (neighborhood or village)
Address 6 CONANT ST
Building ID 1567
Parcel No. (PID) 06-4-172-0
Mapbase # 06-4-172
Building Area 830.54
Historic Name
Present Use residential
Original Use Residential
Date of Construction 1840-1860
Source NR Nomination
Style/Form Greek Revival
Architect/Builder
Exterior Material clapboard
Foundation brick
Wall/Trim wood
Roof Side gable
Outbuildings/Secondary Structures
 1 cottage (c. 1960)

Major Alterations (with dates)

shed dormer; replacement windows (some)

Condition Good
Moved no yes **Date**
Acreage 0.06
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

This building is a 1-story, 5-bay center entry cottage. The side gable roof has a metal-clad chimney at the ridge and a shed dormer on the rear slope; partial cornice returns. Corner pilasters and frieze frame the primary facade. The main entry is a recessed plank door with diamond-shaped pane; flanking pilasters; concrete stoop with brick side walls. Windows are generally 6/6 DHS except a set of paired 1/1 DHS on the south facade. The wood surrounds for the 6/6 wood DHS windows abut the frieze.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*