

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 3 ATLANTIC AVE
Building ID 901
Parcel No. (PID) 07-2-091-0
Mapbase # 07-2-091
Building Area 1161.859
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1860
Source NR Nomination
Style/Form Greek Revival
Architect/Builder
Exterior Material wood shingle
Foundation brick, concrete block
Wall/Trim wood
Roof cross gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

addition (c. 1950)

Condition Good
Moved no yes **Date**
Acreage 0.07
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update
Assessor's Number **USGS Quad** **Area(s)** **Form Number**

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

3 Atlantic Avenue is a 1 1/2-story, 4-bay 3/4 cottage with side ell and cross gable section in rear. The building faces southward. The side gable roof is clad in asphalt shingles; large interior peak brick chimney. The main entrance consists of a wood panel door with wood surround containing pilasters with fluted tops, historic wood fanlight and denticulated cap. Fenestration includes 6/6 vinyl DHS with surrounds wrapped in vinyl; 6/6 wood window in gable end at attic; 2/2 wood DHS in rear (north) and missing window in upper story of this façade. An enclosed vestibule is located at the corner where the main block and ell meet. This vestibule has a hipped roof with overhanging eave. A secondary entry here consists of a panel door and wood screen. A single-pane wood casement window is adjacent to this door.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*