

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Town Provincetown
Place (*neighborhood or village*)
Address 7 CARVER ST
Building ID 1706
Parcel No. (PID) 07-2-181-0
Mapbase # 07-2-181
Building Area 1774.545
Historic Name
Present Use residential
Original Use Residential
Date of Construction 1840
Source NR Nomination
Style/Form Greek Revival
Architect/Builder
Exterior Material clapboard
Foundation brick
Wall/Trim wood
Roof Cross gable

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Outbuildings/Secondary Structures

1-story, shed roof, wood shed @ front of property.

Major Alterations (*with dates*)

Skylight and modern panel aluminum door.

Condition Good
Moved no yes **Date**
Acreage 0.109
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (*month/year*) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

7 Carver Street is a 1 1/2-story, 5-bay building with rear ell. The building is clad in clapboard on the front façade and wood shingle on secondary facades and on the dormer. The cross gable roof is clad in asphalt shingles; partial returns; frieze below eaves; shed dormer on front roof slope. Corner pilasters present. Fenestration includes 6/6 vinyl DHS with wood surrounds. The main entry is offset, located in the 2nd bay from north end, and consists of a pane and panel aluminum door with wood storm; broken pediment hood with square posts and pilasters against buildings; accessed by brick steps. A 1-story shed roof enclosed porch is located on the southern façade contains a secondary entrance with multi-pane wood door and pane and panel wood historic storm door accessed on the west by brick steps. On south side of porch there are 6 consecutive single-pane fixed windows. A 1-story rear ell section has a shed dormer; an additional 1-story shed roof section is attached to the rear of the ell.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*