

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 10 CUDWORTH ST
Building ID 40
Parcel No. (PID) 07-4-012-0
Mapbase # 07-4-012
Building Area 1002.191
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1820
Source Tax assessment
Style/Form Astylistic
Architect/Builder
Exterior Material wood shingle
Foundation stuccoed
Wall/Trim wood
Roof Side gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Rear ell; replacement windows; dormer

Condition Good
Moved no yes **Date**
Acreage 0.114
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

10 Cudworth Street is a 1 1/2-story, 3-bay dwelling with rear ell. The side gable roof has a centered brick chimney at the ridge; shed dormer on rear of main roof abuts the roof of the rear ell. Primary entry (facing west) has panel door with storm and 2-light transom. Secondary entrance on north façade of rear ell. Fenestration includes 6/6 false divided replacement vinyl windows with inoperable louvered shutters; north gable end also has 2 small wood 2/2 DHS; 6/6 DHS window on rear ell, north facade. 1-story rear ell with gable roof and stuccoed chimney. 1-story shed roof section on rear of ell.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*