

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 10 ALDEN ST
Building ID 20
Parcel No. (PID) 12-1-028-0
Mapbase # 12-1-028
Building Area 808.352
Historic Name
Present Use residential-multi-unit
Original Use Residential
Date of Construction 1850-1880
Source NR Nomination
Style/Form Astylistic
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof gable and ell
Outbuildings/Secondary Structures

Major Alterations (with dates)

addition (early 20th cent.); completely renovated recently (2004).

Condition Good
Moved no yes **Date**
Acreage 0.176
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

10 Alden Street is a 2-story, 3-bay side gable building with a projecting front ell. The building is clad in wood shingles. Gable roofs have partial returns; gable dormers; shed wall dormer in main section, front (east) slope; inset gable dormer and skylight on north roof slope of ell. Doors are 4-pane and panel; there is no obvious main entry. Doors are located in east and south facades of the main block and in the southern and northern facades of the ell. Windows are replacement 2/2 vinyl DHS. Second-story deck in rear.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*