

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 16 ALDEN ST
Building ID 324
Parcel No. (PID) 12-1-030-0
Mapbase # 12-1-030
Building Area 995.956
Historic Name
Present Use Residential - Multi-unit
Original Use Residential
Date of Construction 1850-1870
Source NR Nomination
Style/Form Astylistic
Architect/Builder
Exterior Material wood shingle
Foundation obscured
Wall/Trim wood
Roof Side gable
Outbuildings/Secondary Structures
 1-story shed

Major Alterations (with dates)

replacement door; skylight; entry, sash & siding (20th cent.)

Condition Good
Moved no yes **Date**
Acreage 0.099
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

16 Alden Street is a 1 1/2-story, 5-bay building - the primary façade faces south. Side gable roof has partial cornice returns; box cornice, frieze below eaves; shed dormer in south roof slope; skylight; larger shed dormer on north roof slope. Main entry contains a replacement door with simple shed hood above. Windows are 2/1 DHS. Window to right of door is a bay with copper hipped roof and 1/1 DHS. An exterior wood stair and 2nd-story deck and entrance are located at the rear.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*