

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 18 ALDEN ST
Building ID 415
Parcel No. (PID) 12-1-031-0
Mapbase # 12-1-031
Building Area 1112.051
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1850>
Source NR Nomination
Style/Form Astylistic
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof Side gable
Outbuildings/Secondary Structures
 1 secondary building

Major Alterations (with dates)

Addition (west side); sash & siding (c. 1900)

Condition Fair
Moved no yes **Date**
Acreage 0.077
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

18 Alden Street is a 1 1/2-story, 4-bay cottage, oriented to the south. The building is clad in wood shingles, with bands of staggered shingles on gable end. The side gable roof has partial returns, simple cornice and frieze below eaves. Shed dormer on south slope. Main entry is pane and panel door with simple surround. Fenestration includes 2/2 wood DHS windows with storms; some 1/1 DHS are located on the north façade; 3/3 DHS in dormer. A 1-story addition on the west end features an exterior stair to a roof deck and entrance. The addition contains 6/6 DHS windows, and single-light awning windows are located on the north side of the addition.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*