

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 20 ALDEN ST
Building ID 510
Parcel No. (PID) 12-1-032-0
Mapbase # 12-1-032
Building Area 1262.821
Historic Name
Present Use Residential - Multi-unit
Original Use Residential
Date of Construction 1850
Source Tax assessment
Style/Form Greek Revival, Vernacular
Architect/Builder
Exterior Material wood shingle
Foundation stuccoed
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures
 1 shed

Major Alterations (with dates)

replacement windows; addition; shed dormers (mid-20th cent.).

Condition Good
Moved no yes **Date**
Acreage 0.224
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

20 Alden Street is a 2-story, 4-bay 3/4 cottage. front-gable roof has partial returns and large shed dormers on each slope creating a full second story. The main entry contains a 4-pane and panel door with storm; simple entablature and wood surround; brick stoop. A secondary entrance is located on the southern facade. Fenestration includes 2/2, 4/4 and 1/1 DHS. 1-story addition is located at the rear. Exterior steps lead to a 2nd-story entry at the rear, above the addition.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

There appears to have been a recent window replacement campaign (c. 2003), with 1/1 DHS installed at that time.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*