

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 30 ALDEN ST
Building ID 954
Parcel No. (PID) 12-1-035-0
Mapbase # 12-1-035
Building Area 1285.454
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1850
Source Tax assessment
Style/Form Astylistic
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures
 1 2-story double cottage

Major Alterations (with dates)

Condition Good
Moved no yes **Date**
Acreage 0.385
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

This is a 2-story, 3-bay sidehall dwelling oriented toward the south. The front-gable roof has partial returns, brick chimney in east roof slope. The main entry contains a pane and panel door with simple surround. Windows are 6/6 DHS - some wood, some vinyl replacement. 2nd-story windows are directly below the eaves. A 1-story addition is located at the rear (north). An open porch with square posts wraps around the front and east facades, including the addition. A secondary entrance is located on the east façade of the addition.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*