

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Town Provincetown
Place (neighborhood or village)
Address 7 ALDEN ST
Building ID 1696
Parcel No. (PID) 12-1-044-0
Mapbase # 12-1-044
Building Area 901.166
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1850
Source Tax assessment
Style/Form Greek Revival
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof side gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

entry, sash & siding altered (20th cent.)

Condition Good
Moved no yes **Date**
Acreage 0.046
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

7 Alden Street is a 1 1/2-story, 3 bay building with an asphalt shingle-clad side gable roof. Gable dormers are located on south and north roof slopes; partial returns and skylights. A painted board across gable end creates a pediment effect. A frieze below the eaves and corner boards frame the facades. The building is clad in wood shingles, with asphalt siding on the north façade. The main entry is a central pane and panel aluminum door with storm door. The door is flanked by oriel window to the left and a bay window to the right. Both of these contain modern single-pane vinyl casements and wood shingle cladding below. Other fenestration includes 2/1 wood DHS, 6/6 wood DHS, and an oriel window supported by wood braces. Shutters are inoperable. A 1-story ell is located to the rear, with a secondary entrance on the south façade.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*