## MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

## **Photograph**

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll Negative(s)



## **Sketch Map**

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

**Town** Provincetown

Place (neighborhood or village)

Address 7 JOHNSON ST

Building ID 1738

Parcel No. (PID) 12-1-111-0 Mapbase # 12-1-111

Building Area 1397.661

**Historic Name** 

Present Use Residential
Original Use Residential
Date of Construction 1870-1880

Source NR Nomination

Style/Form Italianate

Architect/Builder

Exterior Material clapboard

Foundation brick
Wall/Trim wood

Roof cross gable

**Outbuildings/Secondary Structures** 

1 garage

Major Alterations (with dates)

Replacement windows

**Condition** Good

Moved ✓ no ☐ yes Date

Acreage 0.098

Setting

Recorded by Vanessa Zeoli

Organization Kise Straw & Kolodner

Date (month/year) April 2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSI		ON			
FORM B - BUILDING					
ARCHITECTURAL DESCRIPTION	see continuation sheet				
Describe architectural feaures. Evaluate the characteristic			munity		
7 Johnson Street is a 2-story, 3-bay building. The crosconcrete block chimney on south rear (east). A shed are present. The main entry consists of paired pane a brackets; accessed by brick steps and wrought iron has smaller version of the flat hood and brackets found at the square bay window to left of door with decorative cornifloor of the front facade have flat shallow hoods and pabalusters is located at the southwest corner of the build	s gable roof is clad in asphalt dormer on the north roof slop nd panel wood historic doors indrail. A secondary entrance the primary entry. Fenestratic ce has 3 thin windows across aired brackets. A hipped roof	shingles; partial corn be spans entire length with Victorian wood s e is located on the sou on includes an attic with the front and 1 on ea c; 2-story open porch w	ice returns, Victoria and is clad in wood torms with flat hood ath façade, offset fro indow on front facac ach side; 1/1 vinyl E vith square posts, b	shingles. supported the gaste with 6/6 DHS; wind rackets, a	Corner boards d by elaborative ble, with a wood DHS; a lows on the 2nd and turned
HISTORICAL NARRATIVE	see continuation sheet				
Discuss the history of the building. Explain its associations played within the community.	with local (or state) history. In	clude uses of the buildi	ng, and the role(s) the	e owners/o	eccupants
BIBLIOGRAPHY and/or REFERENCES	see continuation sheet				
Recommended for listing in the National Register Criteria Statement form.	er of Historic Places. If check	ed, you must attach a	completed Nationa	l Register	