

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 5 JOHNSON ST
Building ID 1433
Parcel No. (PID) 12-1-112-0
Mapbase # 12-1-112
Building Area 927.738
Historic Name
Present Use residential
Original Use Residential
Date of Construction 1875
Source Tax assessment
Style/Form Astylistic
Architect/Builder
Exterior Material vinyl
Foundation brick
Wall/Trim vinyl
Roof Cross gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Porch enclosed (1970s)

Condition Good
Moved no yes **Date**
Acreage 0.061
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

5 Johnson Street is a 2-story, 2-bay dwelling. The cross gable roof is clad in asphalt shingles; brick chimney at roof ridge; partial returns. The wall of the second story flares out over the first story. A large cross-gable wall dormer is located on the south façade - this interrupts the cornice and flares out between the first and second stories. The primary entrance includes an aluminum panel door offset to the right with vinyl 3-pane sidelights and modern storm. Fenestration includes 1/1 vinyl DHS; triangular multi-pane-over-one wood DHS (Queen Anne); narrow paired 1/1 vinyl DHS adjacent to the door; inoperable shutters; paired single-pane vinyl casements in the basement.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*