

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

| Roll | Negative(s) |
|------|-------------|
| | |



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 10 JOHNSON ST
Building ID 42
Parcel No. (PID) 12-1-120-0
Mapbase # 12-1-120
Building Area 1093.922
Historic Name Silas Mott House
Present Use Residential
Original Use Residential
Date of Construction 1850
Source NR Nomination
Style/Form Greek Revival
Architect/Builder
Exterior Material clapboard
Foundation brick
Wall/Trim wood
Roof gable front & ell
Outbuildings/Secondary Structures

Major Alterations (with dates)

cladding altered (1970s); addition; replacement windows.

Condition Good
Moved no yes **Date**
Acreage 0.103
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

10 Johnson Street is a 1 1/2-story, 5-bay gable front and ell dwelling with a rear addition. The roof has partial cornice returns; frieze below eaves; brick chimney at ridge in side ell. Corner pilasters are present. The main entry is located in the gable front portion; large surround with entablature, sidelights; panel door; wood stoop. A secondary entry located in the side ell has smaller scale surround and pane and panel door. Windows are 2/1 wood DHS replacements with storms. 1-story shed roof rear addition.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*