

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 4 CENTER ST
Building ID 1200
Parcel No. (PID) 12-1-129-0
Mapbase # 12-1-129
Building Area 1254.566
Historic Name former Methodist Parsonage
Present Use Residential
Original Use Residential
Date of Construction 1870
Source Tax assessment
Style/Form Second Empire
Architect/Builder
Exterior Material clapboard
Foundation brick
Wall/Trim wood
Roof mansard
Outbuildings/Secondary Structures

Major Alterations (with dates)

replacement windows (1988); Closed off front entry

Condition Good
Moved no yes **Date**
Acreage 0.08
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

This is a 2-story, 3-bay sidehall dwelling, formerly the Methodist parsonage. The mansard roof has gable dormers. Unique trim is the same or similar on all elements - includes dentiled cornice with wide frieze and paired brackets. The main entry is closed up; it is shaded by a flat hood with end brackets. Any secondary entrance is not visible from the street. Windows are replacement 1/1 DHS. Large entablatures over 1st story windows, and smaller entablatures over 2nd story windows. 2-story rear ell.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

As per Josephine Del Deo (1977): "parsonage for Center Methodist Church 1860"

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*