

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Town Provincetown
Place (neighborhood or village)
Address 596 COMMERCIAL ST
Building ID 1546
Parcel No. (PID) 15-3-057-0
Mapbase # 15-3-057
Building Area 2627.372
Historic Name
Present Use Residential - Multi-unit
Original Use Residential
Date of Construction 1950
Source Tax assessment
Style/Form Contemporary
Architect/Builder
Exterior Material clapboard
Foundation stuccoed
Wall/Trim wood
Roof Side gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Altered fenestration; contemporary rebuilding

Condition Good
Moved no yes **Date**
Acreage 0.187
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) March 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

596 Commercial St. is a 1-1/2-story, 3-bay condominium building; side-gable roof is sheathed in asphalt roof shingles; shed dormer on rear roof slope; skylights in front roof slope; exterior is clad in clapboard siding on the primary façade with wood shingles on the secondary facades; wood trim; the fenestration has been altered and includes paired casement windows on the side façades, right side façade contains a single-light casement with arched window pane above, some windows contain 1/1 DHS with storms; three large inset gable dormers with sliding glass doors creating 2nd-story decks for each condo unit; 1-story, small shed-roof addition for front entry for end unit on left end; central entry vestibule for middle unit with full glass door and sliding screen; 2nd story of rear façade overhangs the 1st story and is supported by Doric columns.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*