

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 14 BRADFORD ST
Building ID 220
Parcel No. (PID) 06-4-071-0
Mapbase # 06-4-071
Building Area 1207.971
Historic Name
Present Use Residential - Multi-unit
Original Use Commercial
Date of Construction 1850-1870
Source Tax assessment
Style/Form Astylistic
Architect/Builder
Exterior Material clapboard
Foundation brick
Wall/Trim wood
Roof Cross gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Replacement windows; multi-unit conversion

Condition good
Moved no yes **Date**
Acreage 0.031
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) 1/13/2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

14 Bradford St. is a 1 1/2 story 4-bay building with a gable front and ell roof. The gable end has a 1/1 DHS window. The building has a modern central entry door, and is flanked by 2 sets of paired 1/1 DHS on each side; There is a frieze below ell eave. Porch has a concrete block stoop. The right side fascia contains exterior steps to 2nd story entry containing a modern door flanked by 1/1 DHS windows. The left side façade is clad in clapboard siding, has a shed dormer with 1/1 replacement DHS. There is a frieze at the basement level windows.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*