

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 12 BRADFORD ST
Building ID 129
Parcel No. (PID) 06-4-072-0
Mapbase # 06-4-072
Building Area 1259.657
Historic Name
Present Use Residential - Multi-unit
Original Use Residential
Date of Construction 1890
Source Tax assessment
Style/Form Colonial Revival
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof Cross gable
Outbuildings/Secondary Structures
 1 garage

Major Alterations (with dates)

Replacement windows and porch, c. 1930. 1-story rear addition.

Condition Good
Moved no yes **Date**
Acreage 0.074
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) 1/8/2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

This is a 1 1/2-story, sidehall cottage with an ell. The gable end has partial returns, and there is a frieze below the eaves of the ell. The ell also extends to the rear of the building. A large shed dormer was added to the southern roof slope. A gabled dormer is located in the front roof slope of the side ell. Windows are historic and replacement 6/1 DHS, which are typical of the Colonial Revival period. The front entry porch, with a flat roof and Doric columns, is also typical of the period. Recently resided. Porch contains a brick stoop. Multi-pane storm wood door. The right side façade contains 6/1 DHS and 2 secondary entries - one with a wood deck. The left side façade contains 6/1 DHS. The rear façade contains a 1-story addition with entry and 6/1 DHS window.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*