MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown

Place (neighborhood or village)

Address 34 BRADFORD ST

Building ID 1003

 Parcel No. (PID)
 06-4-167-0

 Mapbase #
 06-4-167

 Building Area
 903.582

Historic Name

Present Use Residential
Original Use Residential

Date of Construction 1880

Source Tax assessment

Style/Form Dutch Colonial Revival

Architect/Builder

Exterior Material wood shingle

Foundation brick
Wall/Trim wood

Roof front gambrel
Outbuildings/Secondary Structures

Major Alterations (with dates)

Condition Good

Moved ✓ no ☐ yes Date

Acreage 0.08

Setting

Recorded by Johnette Davies

Organization Kise Straw & Kolodner

Date (month/year) 2/18/2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION		ON			
FORM B - BUILDING					
			· <u>·</u>		
ARCHITECTURAL DESCRIPTION	see continuation sheet				
Describe architectural feaures. Evaluate the characteristic. 34 Bradford Street is a 2-story, 3-bay dwelling with a ce Windows flanking the front door are grouped 6/1 DHS to top of the gable end. The roof has partial cornice return through the main roof and shed dormer eaves. The posingle 6/1 DHS. The left side façade contains paired ar storm door and paired 4-light casements. Also on this façade contains a 2-story addition has concrete block for the story addition has concrete block for	entral entry. The entry has a flanked by 4/1 DHS wood with the same there are shed dormorch contains a brick stoop. The single 6/1 DHS with wood façade, the shed dormer extractions are stored to the single flat the shed dormer extractions.	broken pediment hoch n storms. Other wind ers on each roof slope The right side façade to surrounds, an exteric ends to become main	od, supported by bat lows are 6/1 DHS. The area of the control of	There is a chimney eet contair econdary estory secti	a fanlight in the extends upward ns paired and entrance with ion. The rear
HISTORICAL NARRATIVE	see continuation sheet				
Discuss the history of the building. Explain its associations played within the community.			ng, and the role(s) the	e owners/o	occupants
BIBLIOGRAPHY and/or REFERENCES	see continuation sheet				
Recommended for listing in the National Register Criteria Statement form.	er of Historic Places. If check	ed, you must attach a	completed Nationa	l Register	r