

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 43 BRADFORD ST
Building ID 1303
Parcel No. (PID) 07-2-011-0
Mapbase # 07-2-011
Building Area 1512.509
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1852
Source Tax assessment
Style/Form Italianate
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures shed

Major Alterations (with dates)

Rear addition.

Condition Good
Moved no yes **Date**
Acreage 0.134
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) 2/18/2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

43 Bradford Street is a 1 1/2-story 3-bay, Italianate-style sidehall dwelling; the front-gable roof is clad in asphalt shingles, the eave is boxed with aluminum, an interior brick chimney is located at peak, partial cornice returns exist and a shed dormer is in the north roof slope; the exterior is clad in wood shingles and the foundation is brick; the fenestration includes 2/2 wood DHS with storms installed, a flat-roofed bay window is located to the left of the door, two 2/2 wood DHS windows in the front wall of the bay and 1/1 wood DHS on side, shed dormer has 6/1 wood DHS, the rear ell has a modern Chicago-style window and modern 1/1 DHS and there are panels below the windows; the primary entrance consists of a wood pane and panel door with a storm door, and a flat-roofed hood supported by brackets

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*