

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Town Provincetown
Place *(neighborhood or village)*
Address 42 BRADFORD ST
Building ID 1277
Parcel No. (PID) 07-2-061-0
Mapbase # 07-2-061
Building Area 1841.568
Historic Name
Present Use Commercial/multi-unit Residential
Original Use Residential
Date of Construction 1850-1880
Source NR Nomination
Style/Form Astylistic
Architect/Builder
Exterior Material wood shingle
Foundation concrete block
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Major Alterations *(with dates)*

Storefront added, 1970s.

Condition Good
Moved no yes **Date**
Acreage 0.126
Setting

Recorded by Johnette Davies

Organization Kise Straw & Kolodner

Date *(month/year)* 2/18/2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

This is a 1 1/2-story, 3-bay former dwelling that is now a commercial building. A storefront was added in the 1970s, which includes a central double door entry and plate glass display windows. The gable end, facing the street, has partial cornice returns and three 1/1 DHS windows with wood trim. Doors are full glass and metal. Windows have brick sills. The right façade contains single-light awning windows, skylight, gable dormer with 1/1 DHS, and exterior steps to 2nd story entry. The left side façade contains skylights, single-light awning windows, rear addition and exterior steps to roof deck on 1-story rear addition. Reclad with wood shingles in 2004.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*