# MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

## MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

### Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.



## **Sketch Map**

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town	Provincetown
Place (neighborhood or village)	
Address	46 BRADFORD ST
Building ID	1336
Parcel No. (PID)	07-2-062-0
Mapbase #	07-2-062
Building Area	5353.945
Historic Name	Community Center
Present Use	Municipal
Original Use	Municipal
Date of Construction 1930	
Source	Tax assessment
Style/Form	Colonial Revival
Architect/Builder	
Exterior Material	wood shingle
Foundation	poured concrete
Wall/Trim	wood
Roof	Side gable
Outbuildings/Secondary Structures	

Major Alterations (with dates)

Condition Good Moved 🖌 no 🗌 yes Date 0.452 Acreage **Recorded by** Johnette Davies Setting Organization Kise Straw & Kolodner **Date** (month/year) 2/18/2004 new update Form Status Assessor's Number USGS Quad Form Number Area(s)

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

## MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

#### ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural feaures. Evaluate the characteristics of this building in terms of other buildings in the community.

The Community Center at 46 Bradford Street is a 1-story, 5-bay building with a central entry. The side gable roof has a domed cupola at the center of the roof ridge, and a brick chimney rises from the rear roof slope. The central entry has a pediment entry porch supported by square columns. The entry has paired pane and panel doors with a fanlight above. Windows on the primary façade are 8/12 replacement DHS with snap-in muntins. The right façade is clad in wood shingles, contains a 1-story addition with 2-story section and has a lunette in main gable end. The left side façade has a secondary entry with concrete ramp and 8/12 DHS replacement DHS with snap-in muntins, and a covered lunette with keystones in gable end.

#### HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

**BIBLIOGRAPHY and/or REFERENCES** 

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*