## MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

## **Photograph**

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll Negative(s)



## **Sketch Map**

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

**Town** Provincetown

Place (neighborhood or village)

Address 70 BRADFORD ST

Building ID 1757

 Parcel No. (PID)
 07-2-177-0

 Mapbase #
 07-2-177

 Building Area
 1664.972

**Historic Name** 

Present Use Commercial - Lodging

Original Use Residential

**Date of Construction 1850** 

Source Tax assessment
Style/Form Greek Revival

Architect/Builder

Exterior Material clapboard

Foundation brick
Wall/Trim wood

**Roof** Front gable

**Outbuildings/Secondary Structures** 

Major Alterations (with dates)

Victorian alterations, c. 1870-1890. Rear ell addition.

**Condition** Good

Moved ✓ no ☐ yes Date

Acreage 0.093

Setting

**Recorded by** Johnette Davies

Organization Kise Straw & Kolodner

Date (month/year) 3/5/2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

FORM B - BUILDING					
ARCHITECTURAL DESCRIPTION	see continuation s	sheet			
Describe architectural feaures. Evaluate the character	ristics of this building in terms	of other buildings in the com	nmunity.		
Currently "the Bradford-Carver House"; 70 Bradfor alterations have reoriented the building to face Braflanked by pilasters and capped by a heavy entabl original window locations on the Bradford Street fa A shed-roofed dormer was added to this roof slope addition has been added to the rear of the building flat-roofed hood supported by brackets. A gabled main roof ridge of the building. A gable dormer an 1-story square addition with a wood 6/6 DHS window	adford Street. The primary (Cature. The windows have we agade. Corner pilasters are age, and a square bay window (the side of this façade), an dormer is present on the sided skylight are located on the	Carver Street) façade has a cod surrounds and operabalso present. The Bradford was added to the façade d this accommodates a see gable roof slope of this a north roof slope. Roof is	a sidehall entrance, le shutters. The wi d Street façade has luring late 19th-cent econdary entry. Thi addition. A brick chi	and the r ndow trim a frieze b tury altera s entry is imney is lo	ecessed door is is reflected in elow the eaves. tions. An protected by a ocated at the
HISTORICAL NARRATIVE	see continuation s	sheet			
Discuss the history of the building. Explain its associate played within the community.	tions with local (or state) histor	ry. Include uses of the buildi	ng, and the role(s) th	e owners/o	occupants
DIDLIGODADUV		-ht			
BIBLIOGRAPHY and/or REFERENCES	see continuation s	sileet			
Recommended for listing in the National Re	egister of Historic Places. If c	hecked, you must attach a	completed Nationa	al Registe	r