

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Town Provincetown
Place (neighborhood or village)
Address 72-74 BRADFORD ST
Building ID 1765
Parcel No. (PID) 07-4-005-0
Mapbase # 07-4-005
Building Area 1412.103
Historic Name
Present Use Residential - Multi-unit
Original Use Residential
Date of Construction 1850-1870
Source NR Nomination
Style/Form Astylistic
Architect/Builder
Exterior Material wood shingle
Foundation concrete block
Wall/Trim wood
Roof Side gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

alterations, c. 1980s.

Condition Good
Moved no yes **Date**
Acreage 0.1
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) 3/5/2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

72-74 Bradford Street is a 1-story, multi-bay double cottage. There are two panel entry doors, one for each unit, on the primary façade. There are three gabled dormers on the front roof slope, and a brick chimney at the roof ridge. Windows are replacement 1/1 wood DHS with storms installed. A white picket fence borders the property. The building has partial cornice returns. The west façade contains 1/1 DHS with wood surrounds. The rear (north) façade has an altered fenestration with 1/1 DHS, entry doors at each level reached by exterior wood steps.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*