## MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

## **Photograph**

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll Negative(s)



## **Sketch Map**

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

**Town** Provincetown

Place (neighborhood or village)

Address 90 BRADFORD ST

Building ID 1918

Parcel No. (PID) 11-3-062-0 Mapbase # 11-3-062 Building Area 2122.65

Historic Name Fairbanks House

Present Use Commercial - Lodging

Original Use Residential

**Date of Construction 1776** 

Source 1977 Survey

Style/Form Federal

Architect/Builder

Exterior Material clapboard

Foundation brick

Wall/Trim

Roof Hipped

**Outbuildings/Secondary Structures** 

2-story cottage (modern?)

Major Alterations (with dates)

side addition, renovated and restored 1977

**Condition** Good

Moved ✓ no ☐ yes Date

Acreage 0.168

Setting

**Recorded by** Johnette Davies

Organization Kise Straw & Kolodner

Date (month/year) 3/8/2004

Form Status ☐ new ☑ update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTOI FORM B - BUILDING					
ARCHITECTURAL DESCRIPTION	see continuation	n sheet			
Describe architectural feaures. Evaluate the characte	eristics of this building in term	ns of other buildings in the con	nmunity.		
This building is a 2-story, 5-bay former dwelling. I with transom. A flat-roofed hood, supported by el wood DHS with wood trim and shutters. The fron located to the rear of the west façade, and this ac window, with a balustrade along the roof line. A r louver and wood panel.	aborate knee braces, was a t of the property is bordered commodates the inn office.	added to the door surround in the by an iron fence with brick The addition has a multi-p	n the late 19th cent piers. A 1-story sid ane door flanked by	ury. Wind e gable ro a full-heiç	lows are 6/6 oof addition is ght multi-pane
HISTORICAL NARRATIVE	□ see continuation	n sheet			
Discuss the history of the building. Explain its associate played within the community.			ing, and the role(s) th	e owners/o	ecupants
"The Fairbanks Inn" (2004)					
As per Josephine Del Deo (1977): "This house is number of excellent examples in this inventory: To structure at 118 Bradford. The house is in excelle	he Ryder house 4 Winslow,	Preston Hall House, 396 C			
One of its previous owners, David Fairbanks, was century. Quoting from the Provincetown Walking Company, as an agent of the Freeman's Bank of he moved the Freeman's branch to Union Wharf a Savings Bank of which he was secretary (1852-56).	Tour No. 1 the Center of Pr Boston, began the first ban and five years later, with oth	ovincetown. "In the 1840's E king business in town in the ner businessmen, started the	David Fairbanks, a p front parlors of this	artner of the	the Union Wharf s home. In 1846
Previous owners include Captain Eben Snow and	David Faribanks				
BIBLIOGRAPHY and/or REFERENCES	see continuation	n sheet			
"Provincetown Advocate. " April 10, 1975 "Walking Tour No. 1, The Center of Provincetwon	", Provincetown Historical <i>I</i>	Association 12. Folk Art Mus	eum.		
☐ Recommended for listing in the National R	egister of Historic Places. <i>If</i>	checked, you must attach a	a completed Nationa	ıl Register	

Criteria Statement form.