

# MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION  
MASSACHUSETTS ARCHIVES BUILDING  
220 MORRISSEY BLVD  
BOSTON, MA 02125

**Town** Provincetown  
**Place** *(neighborhood or village)*  
**Address** 92 BRADFORD ST  
**Building ID** 1927  
**Parcel No. (PID)** 11-3-063-0  
**Mapbase #** 11-3-063  
**Building Area** 1139.499  
**Historic Name**  
**Present Use** Residential  
**Original Use** Residential  
**Date of Construction** 1850  
**Source** Tax assessment  
**Style/Form** Greek Revival  
**Architect/Builder**  
**Exterior Material** clapboard  
**Foundation** brick  
**Wall/Trim** wood  
**Roof** Front gable  
**Outbuildings/Secondary Structures**

## Photograph

*(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.*

Roll	Negative(s)



## Sketch Map

*Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.*

## Major Alterations *(with dates)*

Skylights; replacement sash and entry door, c. 1900.

**Condition** Good  
**Moved**  no  yes **Date**  
**Acreage** 0.076  
**Setting**

**Recorded by** Johnette Davies  
**Organization** Kise Straw & Kolodner  
**Date** *(month/year)* 3/8/2004  
**Form Status**  new  update

Assessor's Number    USGS Quad    Area(s)    Form Number

*Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.*

# MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

--	--	--	--

### ARCHITECTURAL DESCRIPTION

see continuation sheet

*Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.*

92 Bradford Street is a 2-story, 3-bay sidehall entry dwelling. The full cornice return has an entablature below. The recessed entry door has a monumental surround, including pilasters and a heavy entablature. The door is reached by wood steps and landing. Windows are 6/6 DHS and the windows on the primary façade have wood trim. The windows on the 2nd story abut the entablature. There is a brick chimney in the left (west) roof slope, as well as 2 skylights. There is also an exterior brick chimney. There are wooden decks at each story on the rear of the dwelling. Shutters are inoperable. Basement level contains 2-light windows. The right side façade has a shed dormer with 6/6 replacement DHS. Windows toward rear of main building section are 6/6 and 2/2 wood DHS with storms. The rear ell is clad in wood shingles and contains 2/2 DHS windows with vertical and horizontal muntins.

### HISTORICAL NARRATIVE

see continuation sheet

*Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.*

s1970

### BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*