

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 100 BRADFORD ST
Building ID 60
Parcel No. (PID) 11-3-076-0
Mapbase # 11-3-076
Building Area 1645.654
Historic Name Provincetown Advocate Office
Present Use Commercial
Original Use
Date of Construction 1950-1970
Source NR Nomination
Style/Form Astylistic
Architect/Builder
Exterior Material clapboard
Foundation brick
Wall/Trim
Roof Front gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Condition Good
Moved no yes **Date**
Acreage 0.107
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) January 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

This is a 2 1/2-story, 3-bay building. The 2nd story slightly overhangs the 1st on the side elevation. A section of patterned brickwork veils ventilation utilities. Windows are 12/12 DHS on the 1st story and single-pane bay, fixed pane and casements above. A brick stoop with metal railing leads to a modern door. The left side façade has an interior brick chimney, replacement 1/1 DHS in the 2nd story, canted bay window and 12/12 wood DHS windows in the 1st story. The DHS windows in the 1st story have large metal shutters with bolt mechanisms to keep them open. The rear façade contains 1/1 DHS replacement windows, and paired casements in gable end. The right side façade has exterior wood steps to 3rd story entry and one former entrance filled with brick.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*