

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Town Provincetown
Place (neighborhood or village)
Address 135 BRADFORD ST
Building ID 205
Parcel No. (PID) 12-1-022-0
Mapbase # 12-1-022
Building Area 1926.349
Historic Name
Present Use Commercial
Original Use
Date of Construction 1900>
Source NR Nomination
Style/Form Astylistic
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof cross gable
Outbuildings/Secondary Structures

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Major Alterations (with dates)

Condition Good
Moved no yes **Date**
Acreage 0.091
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) January 2004
Form Status new update
Assessor's Number **USGS Quad** **Area(s)** **Form Number**

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

135 Bradford Street consists of two buildings that are now attached; To the east side, at the corner of Bradford St and Standish Street is a 1 1/2-story, 3-bay, Astylistic commercial building that faces Standish Street; the roof is side-gable and clad in wood shingles; the exterior is clad in wood shingles and the foundation is obscured; the fenestration includes modern fixed-pane windows on the 1st story, and 1/1 vinyl DHS in the gable end and in each of the 3 gable-roofed dormers; The primary entrance is on the left (south) side of the front façade and consists of a vertical plank door with strap hinges; To the west is a 3-story, approximately 5-bay, Astylistic structure that originally served a commercial or industrial purpose; the cross-gable roof is clad in wood shingles and is interrupted by gable wall dormers, the exterior chimney is clad in stucco; the exterior is clad in wood shingles and the foundation is brick; the 2nd floor overhangs a brick 1st floor showing exposed rafters; the fenestration consists of 9/9 wood DHS flanking a central window filled with wood shingles and 6/6 wood DHS in the attic level, gable wall dormers contain 2/12 wood DHS, the ell contains wood shingle-filled picture windows flanked by 4/4 wood DHS, gable wall dormers with 42-pane wood picture windows flanked by 6/6 wood DHS; the primary entrance appears to be a large loading dock door that has been replaced with a modern pedestrian pane and panel door, a secondary entrance consists of a loading dock with a modern pane and panel door

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*