MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

| Town | Provincetown |
|-----------------------------------|-----------------|
| Place (neighborhood or village) | |
| Address | 173 BRADFORD ST |
| Building ID | 396 |
| Parcel No. (PID) | 12-4-073-A |
| Mapbase # | 12-4-073-A |
| Building Area | 810.519 |
| Historic Name | |
| Present Use | residential |
| Original Use | Residential |
| Date of Construction 1890 | |
| Source | Tax assessment |
| Style/Form | Astylistic |
| Architect/Builder | |
| Exterior Material | wood shingle |
| Foundation | concrete block |
| Wall/Trim | wood |
| Roof | Side gable |
| Outbuildings/Secondary Structures | |

Major Alterations (with dates)

Condition Moved 🖌 no 🗌 yes Date 0.237 Acreage **Recorded by** Vanessa Zeoli Setting Organization Kise Straw & Kolodner Date (month/year) Form Status 🔳 new update Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural feaures. Evaluate the characteristics of this building in terms of other buildings in the community.

173 Bradford Street is a 1-story, 2-3-bay, Astylistic residence; The side gable roof is clad in asphalt shingles, and the brick interior chimney is located at the peak; The exterior is clad in wood shingles and the foundation is concrete block; The fenestration includes 6/6 wood DHS with historic 12-pane and 4-pane wood storms and inoperable shutters; The main entrance may be located on south façade at enclosed porch, but this side not visible from street; Wood steps and wood storm door access the enclosed porch; A 1-story shed roof section is located on the east side with vertical board exterior, 6/6 wood DHS and 12-pane wood storms.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. If checked, you must attach a completed National Register Criteria Statement form.