

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

| Roll | Negative(s) |
|------|-------------|
| | |



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 178 BRADFORD ST
Building ID 413
Parcel No. (PID) 12-4-108-0
Mapbase # 12-4-108
Building Area 2265.857
Historic Name
Present Use Commercial - Lodging
Original Use Residential
Date of Construction 1820
Source Tax assessment
Style/Form Astylistic
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof Cross gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Additions, replacement windows

Condition Good
Moved no yes **Date**
Acreage 0.149
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) 1/31/2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

178 Bradford Street is a 1 1/2-story, 4-bay, Astylistic building; the roof is cross gable, a large corbelled brick chimney rises from the center of the roof ridge and an additional corbelled brick chimney is located at the rear; the exterior is clad in wood shingles with wood trim; the fenestration includes replacement 6/6 DHS, some operable shutters on the front façade; the primary entrance has a replacement door with transom and wood surround capped by a decorated broken pediment; an addition on the side of the primary façade has a picture window; additions to the rear and side are 1 and 2 stories in height, with 2/2, 8/8, and 6/6 DHS, and secondary entrances on each side.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

Currently "Snug Cottage"

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*