## MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

## **Photograph**

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll Negative(s)



## **Sketch Map**

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

**Town** Provincetown

Place (neighborhood or village)

Address 634 COMMERCIAL ST

Building ID 1651

Parcel No. (PID) 15-3-073-0

Mapbase # 15-3-073

Building Area 1041.855

**Historic Name** 

Present Use Residential
Original Use Residential

**Date of Construction** 1917 **Source** Owner

**Style/Form** Queen Anne, Vernacular

Architect/Builder

**Exterior Material** wood shingle

**Foundation** 

Wall/Trim wood

Roof clipped gable

Outbuildings/Secondary Structures

Major Alterations (with dates)

**Condition** Good

Moved ✓ no ☐ yes Date

Acreage 0.055

Setting

**Recorded by** Johnette Davies

Organization Kise Straw & Kolodner

**Date** (month/year) December 2003 **Form Status** ■ new ■ update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSI		ON			
FORM B - BUILDING					
ADCUITECTUDAL DESCRIPTION	see continuation shee	•	-		
ARCHITECTURAL DESCRIPTION  Describe architectural feaures. Evaluate the characteristic					
634 Commercial Street is a 2-story, 3-bay dwelling. C 2/2 DHS with operable shutters. The central entry ha posts and balustrades. Eaves and porch roof are em wood deck accesses entry. The right side façade ha	lipped gable roof is sheathed s a wooden storm door. An o bellished with trim. A second	in asphalt shingles. Expen porch wraps aroulary entrance is locate	kterior is clad in woo and the front and side d near the rear, left	e facades,	, with square
HISTORICAL NARRATIVE	see continuation shee	t			
Discuss the history of the building. Explain its association played within the community.			ng, and the role(s) the	e owners/o	ccupants
Owner says its been in her family since c.1920, and r	not many changes have been	made.			
BIBLIOGRAPHY and/or REFERENCES	see continuation shee	t			
Recommended for listing in the National Regis	ter of Historic Places. If check	red, you must attach a	completed Nationa	l Register	